



Total Quality. Assured.

545 E Algonquin Road, Suite H
Arlington Heights, IL 60005 USA

Telephone: 847-439-5667
intertek.com

Published: March 19, 2020
Revised:

Public Notice ID: 20-05
Page 1 of 2

Safety Concern with Intertek Certified Product / Souci de sécurité avec le produit certifié Intertek

Class 2 LED Driver within the Hampton Bay Path Light Set

Notification Type:	Safety / Sécurité
Certification Type:	ETL Listed - US and Canada

Notification

Intertek notifies consumers, retailers and distributors of a potential safety concern involving the Intertek Certified products identified below. / Intertek informe les consommateurs, les détaillants et les distributeurs d'une préoccupation potentielle en matière de sécurité impliquant les produits certifiés Intertek identifiés ci-dessous.

Company Identification

Sterno Home Inc.

Product Identification

Class 2 LED Driver packaged with branded certified product for Hampton Bay Path Light Set (HD33677BK), manufactured by Sterno Home, Models E000-1696, E000-1697, E000-1698, E000-1909, E000-1910. Affected product are labeled with the cETLus certification mark and accompanying control number 4009883. Refer to photos on page 2.

Hazard Involved

Reports of electrical shock hazards related to the AC blades of the driver pulling-out from the Driver while plugged into an outlet receptacle.


What To Do

Use of these products should be immediately discontinued and return to the point of purchase. Distributors and retailers should discontinue sales and return inventories to their suppliers. / L'utilisation de ces produits doit être immédiatement abandonnée et retourner au point d'achat. Les distributeurs et les détaillants doivent cesser les ventes et retourner les inventaires à leurs fournisseurs.

Published: March 19, 2020
Revised:

Public Notice ID: 20-05
Page 2 of 2

Photos and Images



Driver found in Hampton Bay Path Lights HD33677BK pictured below

